


STRUCTURAL MODULAR INNOVATIONS, LLC

P.O. Box 315, 101 Southern Avenue, Strattanville, PA 16258

800-216-7849 / 814-764-5555 / 814-764-5852 FAX

CORRECT PROCEDURE FOR CARRIER RETURN



1. LOAD OUTRIGGERS IN BOTTOM CARRIER
2. COLLAPSE TONGUES OF THE CARRIERS WITHIN 6' OF THE FRONT CROSSMEMBER
3. POSITION TOP CARRIER APPROXIMATELY 3' BEHIND HITCH OF BOTTOM CARRIER
4. PARK CARRIERS IN A LOCATION SO THAT A TRUCK HAS ACCESS TO THEM 24 HOURS A DAY, WITH NO HELP FROM OTHER EQUIPMENT